



# Chemical Consultants INCORPORATED

**AR-20**

**Adhesive Stripper**

## General Description

AR-20 is a specially formulated adhesive stripper. AR-20 will break-down and liquefy solvent and water-based adhesives. AR-20 is an excellent cleaner for the removal of pallet or belt printers adhesives. AR-20 will instantly remove adhesive residue left behind from tape. AR-20 is emulsion and capillary film safe, making it ideal when removing tape and cataloging your screens. AR-20 is excellent for cleaning up over-spray from aerosol adhesives. AR-20 can be used to clean adhesive build-up on printing presses.

### Quick Tip:

**For Best Results:**  
Use a plastic scrapper or putty knife to quickly scrape and remove dissolved adhesive.


## Advantages

- Easy To Use
- Fast Acting
- Low Odor
- Mesh Safe
- Emulsion Safe
- Quickly Dissolves Solvent-Based Adhesives
- Quickly Dissolves Water-Based Adhesives
- High Load Capacity To Reduce Usage

## Application

AR-20 can be applied by a rag, spray bottle, or pneumatic pump system.

1. Apply AR-20 directly to the adhesive. AR-20 will start to liquefy the adhesive within seconds.
2. Remove the dissolved adhesive from the surface with a rag or scrapper.



Sizes Available:

Pint

Quart

4 x 1 Quart

Gallon

4 x 1 Gallon

5 Gallon Pail

55 Gallon Drum